



Specifications

To control the speed of the actuator wire the rheostat or potentiometer capable of handling full actuator current (~6 A) as follows:

